

Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

**Mine Name: Binale 1
Mine ID: 221**

Navajo AUM North Central Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

20074.063.039.0020

April 2012

Part I Site Identification, Location and Status**Site Names and ID numbers as applicable****Mine ID:** 221**Map ID:** NC56**CERCLIS:** NNN000909251**Navajo Abandoned Mine Land Reclamation Program:** NA-0223**Local name / Aliases:** H.H. Benally**Chapter and local area:** Oljato**County:** Navajo **State:** AZ**Lat/Long:** 36.962331879 N / -110.109022735 W**Nearby road and highway:** Indian Route 42 **Local Post Office:** Oljato, AZ**Surface Land Status: check one or more and provide ownership and contact information below**

Tribal Trust Land	<input checked="" type="checkbox"/>	Public lands	<input type="checkbox"/>
Private	<input type="checkbox"/>	Tribal Fee Land	<input type="checkbox"/>
Bureau of Land Mgmt	<input type="checkbox"/>	Allotment	<input type="checkbox"/>
State	<input type="checkbox"/>	Fee land	<input type="checkbox"/>

Subsurface Mineral Rights:

No information on subsurface mineral rights ownership was found in the EPA/AUM Database.

Claim and operator information:

No historical ownership / lease information or documents were identified in the EPA / AUM database.

Number of residential structures within 200 feet of mine: None

Part II Summary of Radiological Readings

Mine ID: 221

Highest gamma radiation measurement: 128,497 counts per minute (cpm)


Background Average: 10,289 cpm **Two Times Background:** 20,578 cpm

Describe any other radiological measurements:

A total of 4,595 gamma radiation measurements were collected from the mine site, ranging from 4,662 cpm to 128,497 cpm. Maximum levels of approximately 125,000 cpm were found at the entrance to the adit, 15,000 cpm were found at the vent hole above the adit, and 15,000 cpm were found at bermed area at the top of the site. The measurements are represented in Figures 1 and 2.

Distribution Chart and Statistics:

Site Gamma Radiation Statistics	
Number of Readings	4,595
Minimum (cpm)	4,662
Maximum (cpm)	128,497
Mean (cpm)	11,392
Median (cpm)	8,032
Standard Deviation	10,896



Part III Status of Reclamation and Mine Waste**Mine ID: 221****The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:****NAMLRP Status of the mine site: Reclaimed: Yes Waste Pile onsite: Yes****NAMLRP Project Number: NA-0223****NAMLRP Mine features: 1 Portal**

The following information was obtained from field observations collected during the 2011 site screening:**Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.****Observed reclamation work and status:****Adits:**

1 adit, stone sealed, approximately 10' x 12', alongside the hiking trail running through the site

Waste Piles:

Waste rock below the adit, down the cliffside, approximately 75' x 25'

Pits:

None Observed

Shafts:

None Observed

Other Debris and Mine Features:

Mining debris (cable, metal scraps, pipe) immediately south of the site

Part IV Site Observations and Environs

Observed Residential Structures (number and human habitation status of structures at the following distances from the mine site):

0 to 200 feet: None Observed

200 feet to 0.25 mile: None Observed

Observed Public or Commercial Structures (schools, clinics, Chapter Houses, places of business and any other structures used by members of the community at the following distances from the mine site):

0 to 200 feet: None observed

200 feet to 0.25 mile: None observed

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed Water Sources (number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine site):

0 to 0.25 miles: Onsite - Bermed area with standing water at top of the site

0.25 miles to 4 miles: None Observed

Sensitive Environments (all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation):

Site is located within Monument Valley Tribal Park

Known Site History (information from interviews with Chapter officials and residents and database review, includes: mine ownership, type of mining operation, period of operation, known amount of production, and any other information provided):

The Binale 1 mine claim consists of an area of 6,532 m². No additional historical ownership / lease information was identified in the EPA / AUM database.

Part V Response Action Summary

Summary of Evaluation Factors:

Accessibility:

Was the mine easily accessible to potential human activity?

Yes

Radiological Measurements:

Were any gamma radiation measurements collected at the mine greater than two times the site-specific background levels?

Yes

Waste Piles:

Were any unreclaimed waste piles observed at the mine with gamma radiation measurements greater than two times the site-specific background levels?

Yes

Structures:

Were any structures observed within 200 feet of the mine?

No

Potential Drinking Water Sources:

Were any potential drinking water sources observed within 4 miles of the mine?

Yes

Reclamation:

Was the mine reported to be previously reclaimed, or did the mine appear to be reclaimed?

Yes

Part VI Photos



Photo 1

Mine Site #221 – Trail through site




Photo 2

Mine Site #221 – Trail through site




Photo 3

Mine Site #221 - Adit



Photo 4

Mine Site #221- Adit



Photo 5

Mine Site #221- Adit



Photo 6

Mine Site #221- Adit



Photo 7

Mine Site #221 – Waste rock below adit



Photo 8

Mine Site #221 – Waste rock below adit



Photo 9

Mine Site #180



Photo 10

Mine Site #180 - Mining debris



Photo 11

Mine Site #180 – Vent pipe above adit



Photo 12

Mine Site #180 – Standing water

Part VII Contact Reports and InformationName: Eugene EsplainTitle or official role (if any): Navajo EPA Superfund ProgramTelephone number: (928) 871-7331Address: PO Box 2946, Window Rock, AZ 86515Information provided: Lead Regulatory Agency

Name: _____

Title or official role (if any): _____

Telephone number: _____

Address: _____

Information provided: _____

Name: _____


Title or official role (if any): _____

Telephone number: _____

Address: _____

Information provided: _____

Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Binale 1 (221)
Oljato Chapter, Navajo Nation



Gamma Radiation Measurements

- < 2X Background
- > 2X Background

Measured as counts per minute (cpm)

Average background 10,289 cpm



Mine Site Boundary



General Slope Direction



Observed Reclamation Feature



Observed Waste Rock



Observed Structure



Observed Adit




0 100 Feet



WESTON
SOLUTIONS

Figure 2 - Gamma Radiation Measurements
Binale 1 (221)
Oljato Chapter, Navajo Nation



Gamma Radiation Measurements

- 0 - 10,000 cpm
- 10,000 - 25,000 cpm
- 25,000 - 50,000 cpm
- 50,000 - 100,000 cpm
- 100,000 - 250,000 cpm
- 250,000 - 500,000 cpm
- 500,000 - 1,000,000 cpm

Mine Site Boundary

General Slope Direction

Observed Reclamation Feature

Observed Waste Rock

Observed Structure

Observed Adit



0 100
Feet



WESTON
SOLUTIONS

Average background 10,289 cpm

Measured as counts per minute (cpm)